

CERTIFICATO D'ISPEZIONE NR. 0014/VE **(INSPECTION CERTIFICATE)**

FILE NO. 25.27248

FORNITORE
SUPPLIER

LEGHORNGROUP SRL - VIA DEGLI ARROTINI 34/36 – LIVORNO (LI)

COSTRUTTORE
MANUFACTURER

LEGHORNGROUP SRL - VIA DEGLI ARROTINI 34/36 – LIVORNO (LI)

DESCRIZIONE MATERIALE / MATERIAL DESCRIPTION

Prodotto sottoposto all'attività / *Product object of the test*

- CERBERUS SEAL

ISPEZIONE ESEGUITA / INSPECTION PERFORMED

Sono state presenziate le prove di antimanomissione dl sigillo di alta sicurezza CERBERUS SEAL previste dalla norma ISO 17712:2013 punto 6.

The tamper-evident capabilities test of high-security seal CERBERUS SEAL have been witnessed according to ISO 17712:2013 clause 6.

DOCUMENTI DI RIFERIMENTO / REFERENCE DOCUMENTS

Le prove effettuate sul materiale sono state eseguite in conformità con i seguenti documenti:
Activities have been performed according to the following documents:

- STANDARD ISO 17712:2013 clause 6.

RISULTATI / RESULTS

I risultati ottenuti dalle verifiche e dai collaudi effettuati sono riportati in dettaglio nei seguenti documenti:

The test results of the activities performed are detailed in the following documents

- Test report N° 0007 – dated 06/06/2025 issued by Leghorngroup and witnessed by SGS and SGS inspection report N° 25.500.0515 rev.0 dated 16/06/2025.

SGS ICS Italia S.r.l.
On behalf
Rosalba Fanale



Data di emissione/Issuance date: 17/06/2025

1/2



This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS ICS Italia S.r.l.
Via Caldera, 21
20153 Milano
02/73931

CERTIFICATO D'ISPEZIONE NR. 0014/VE **(INSPECTION CERTIFICATE)**

CONCLUSIONI / CONCLUSIONS

Le prove di antimanomissione effettuate sono risultate, per le attività eseguite, conformi ai requisiti dei documenti di riferimento e in particolare alla norma ISO 17712:2013 punto 6.
The appropriate testing activities have been performed and the results conform to the requirements outlined in ISO 17712 :2013 clause 6.

- This Certificate Is Composed of 2 Pages -


Above findings are limited to the date and place of intervention only.
The company is neither an insurer nor a guarantor and disclaims all liability in such capacity.
Our inspection/certification does not absolve the manufacturer/seller from their contractual obligations towards their buyer.

SGS ICS Italia S.r.l.
On behalf
Rosalba Fanale



Data di emissione/Issuance date: 17/06/2025

2/2



This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS ICS Italia S.r.l.
Via Caldera, 21
20153 Milano
02/73931